

January 31, 2005

Mr. Christopher M. Crane, President  
and Chief Executive Officer  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

SUBJECT: BRAIDWOOD STATION, UNIT 2 - RESPONSE TO NUCLEAR REGULATORY  
COMMISSION BULLETIN 2003-02, "LEAKAGE FROM REACTOR PRESSURE  
VESSEL LOWER HEAD PENETRATIONS AND REACTOR COOLANT  
PRESSURE BOUNDARY INTEGRITY" (TAC NO. MC0524)

Dear Mr. Crane:

On August 21, 2003, the U.S. Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage. The bulletin also requested these addressees to provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next, and subsequent, refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural, and leakage integrity of the RPV lower head penetrations.

By letter dated September 22, 2003, (ML032691399), Exelon Generation Company, LLC (Exelon) provided its response to this request. Exelon committed to perform a bare-metal visual examination of the RPV lower head surface, and on 100 percent of all 58 RPV lower head penetrations, during the fall 2003 refueling outage at Braidwood Station (Braidwood), Unit 2. In its same response, Exelon indicated that the extent, and frequency of subsequent visual examinations of the RPV lower head penetrations, beyond the fall 2003 refueling outage, will depend upon the appropriate NRC and industry guidance as well as the standardized EGC Procedure ER-AP-331-1001, "Boric Acid Corrosion Control (BACC) Inspection Locations, Implementation, and Inspection Guidelines." The NRC staff notes that there are a number of ongoing industry, and NRC staff activities related to developing criteria for RPV lower head penetration inspections. The NRC staff expects that the criteria for these inspections will involve periodic bare-metal visual examinations or their equivalent.

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection, and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits, and any corrective actions taken as a result of indications found.

By letter dated January 15, 2004, (ML040210555), Exelon provided a summary of its inspection results at Braidwood, Unit 2. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Exelon's responses to NRC Bulletin 2003-02, the NRC staff finds that Exelon has met the reporting requirements of the bulletin for Braidwood, Unit 2. Accordingly, technical assignment control no. MC0524 is closed for Braidwood, Unit 2.

Sincerely,

*/RA/*

George F. Dick, Senior Project Manager, Section 2  
Project Directorate III  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. STN 50-457

cc: See next page

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection, and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits, and any corrective actions taken as a result of indications found.

By letter dated January 15, 2004, (ML040210555), Exelon provided a summary of its inspection results at Braidwood, Unit 2. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Exelon's responses to NRC Bulletin 2003-02, the NRC staff finds that Exelon has met the reporting requirements of the bulletin for Braidwood, Unit 2. Accordingly, technical assignment control no. MC0524 is closed for Braidwood, Unit 2.

Sincerely,

**/RA/**

George F. Dick, Senior Project Manager, Section 2  
Project Directorate III  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket No. STN 50-457

cc: See next page

Distribution:

PUBLIC	SMonarque	DPassehl	PCoates
PDIII-1 RF	GSuh	GDick	
PDIII-2 RF	DLPM DPR	ESullivan	

ADAMS ACCESSION NUMBER: **ML050030255**

OFFICE	PDIII-2/PM	PDIII-2/LA	LPM	EMCB	PDIII-2/SC
NAME	GDick	PCoates	SMonarque	ESullivan	GSuh
DATE	1/31/05	1/31/05	01/5/05	01/12/05	1/31/05

**OFFICIAL RECORD COPY**

Braidwood Station Units 1 and 2

cc:

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
801 Warrenville Road  
Lisle, IL 60532-4351

Document Control Desk - Licensing  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Mr. Dwain W. Alexander, Project Manager  
Westinghouse Electric Corporation  
Energy Systems Business Unit  
Post Office Box 355  
Pittsburgh, PA 15230

Joseph Gallo  
Gallo & Ross  
1025 Connecticut Ave., NW, Suite 1014  
Washington, DC 20036

Ms. Bridget Little Rorem  
Appleaseed Coordinator  
117 N. Linden Street  
Essex, IL 60935

Howard A. Learner  
Environmental Law and Policy  
Center of the Midwest  
35 East Wacker Dr., Suite 1300  
Chicago, IL 60601-2110

U.S. Nuclear Regulatory Commission  
Braidwood Resident Inspectors Office  
35100 S. Rt. 53, Suite 79  
Braceville, IL 60407

Ms. Lorraine Creek  
RR 1, Box 182  
Manteno, IL 60950

Illinois Emergency Management  
Agency  
Division of Disaster Assistance &  
Preparedness  
110 East Adams Street  
Springfield, IL 62701-1109

Chairman  
Will County Board of Supervisors  
Will County Board Courthouse  
Joliet, IL 60434

Attorney General  
500 S. Second Street  
Springfield, IL 62701

George L. Edgar  
Morgan, Lewis and Bockius  
1111 Pennsylvania Ave, NW  
Washington, DC 20004

Braidwood Station Plant Manager  
Exelon Generation Company, LLC  
35100 S. Rt. 53, Suite 84  
Braceville, IL 60407-9619

Site Vice President - Braidwood  
Exelon Generation Company, LLC  
35100 S. Rt. 53, Suite 84  
Braceville, IL 60407-9619

Senior Vice President, Nuclear Services  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Vice President of Operations - Mid-West  
Pressurized Water Reactors  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Chairman, Ogle County Board  
Post Office Box 357  
Oregon, IL 61061

Regulatory Assurance Manager - Braidwood  
Exelon Generation Company, LLC  
35100 S. Rt. 53, Suite 84  
Braceville, IL 60407-9619

Director - Licensing and Regulatory Affairs  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Associate General Counsel  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Vice President - Licensing and Regulatory Affairs  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Manager Licensing - Braidwood, Byron and LaSalle  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555